

**APPENDIX C**

**Culvert Inspection Reports**



DeLUCA-HOFFMAN ASSOCIATES, INC.  
CONSULTING ENGINEERS

778 MAIN STREET  
SUITE 8  
SOUTH PORTLAND, MAINE 04106  
TEL. 207 775 1121  
FAX 207 879 0896

**CULVERT INSPECTION REPORT**  
EASTERN TRAIL EXTENSION PROJECT  
From Milliken Mills Road in Old Orchard Beach to  
Thornton Academy in Saco

**Inspector:** Andrew Morrell

**Inspection Date:** 9/28/09

| INSPECTION #1                             | Inlet   | Outlet   |
|---|---|--|
| <b>Approximate Location:</b>              | Thornton Academy Campus parking area for middle school southeast of baseball field    | Thornton Academy Campus parking area for middle school southeast of baseball field |
| <b>Any nearby existing features:</b>      | Thornton Academy  | Thornton Academy   |
| <b>Size:</b>                              | CB with 8-inch outlet   | 8" PVC   |
| <b>Material:</b>                          | PVC Culvert   | PVC Culvert  |
| <b>Condition of Culvert:</b>              | Good  | Good   |
| <b>Does pipe appear to be undersized:</b> | No  | No   |
| <b>Flow Direction:</b>                    | North to south under parking area   | North to south under parking area  |
| <b>Sedimentation:</b>                     | No  | Unknown  |
| <b>Erosion:</b>                           | Yes   | Unknown  |
| <b>General Comments:</b>                  | - CB not inspected as part of this review<br>- Minor erosion along EOP to be repaired | - Outlet cannot be found<br>- May be buried by piled debris                        |



Catch basin inlet looking southeast



Catch basin inlet looking northwest



Potential outlet ditch looking southeast

**Inspector:** Andrew Morrell

**Inspection Date:** 9/28/09

| INSPECTION #2                             | Inlet   | Outlet  |
|---|---|---|
| <b>Approximate Location:</b>              | West of Trail in Segment A between east/west travel lanes on I-195 west of U.S. Route 1 Interchange   | East of Trail & I-195 in Segment A west of U.S. Route 1 Interchange – Station 56+64 (Trail stationing)  |
| <b>Any nearby existing features:</b>      | I-195   | I-195   |
| <b>Size:</b>                              | CB with 18-inch outlet  | 18-inch   |
| <b>Material:</b>                          | RCP Culvert   | RCP Culvert   |
| <b>Condition of Culvert:</b>              | Unknown   | Good  |
| <b>Does pipe appear to be undersized:</b> | Unknown   | No  |
| <b>Flow Direction:</b>                    | Northeast to southwest under I-195 (eastbound)  | Northeast to southwest under I-195 (eastbound)  |
| <b>Sedimentation:</b>                     | Unknown   | No  |
| <b>Erosion:</b>                           | No  | No  |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- CB not inspected as part of this review</li> <li>- CB has 6'x6' paved apron within ditch bottom</li> </ul> | <ul style="list-style-type: none"> <li>- RCP pipe chipped at top of pipe</li> <li>- Proposed Trail will cross over the outlet</li> <li>- Culvert extension may be required</li> </ul> |



Catch basin inlet looking southeast



Catch basin inlet looking northwest



Outlet looking northeast



Outlet outfall looking southwest

**Inspector:** Andrew Morrell

**Inspection Date:** 9/28/09

| INSPECTION #3                             | Inlet   | Outlet   |
|---|---|--|
| <b>Approximate Location:</b>              | West of Trail in Segment A between east/west travel lanes on I-195 west of U.S. Route 1 Interchange   | East side of Trail & I-195 in Segment A west of U.S. Route 1 Interchange – Station 59+24 (Trail stationing)  |
| <b>Any nearby existing features:</b>      | I-195 (between east/west travel lanes)  | I-195/Hannaford Bros. Co.  |
| <b>Size:</b>                              | CB with 18-inch outlet  | 18-inch  |
| <b>Material:</b>                          | Unknown   | RCP Culvert  |
| <b>Condition of Culvert:</b>              | Unknown   | Good   |
| <b>Does pipe appear to be undersized:</b> | Unknown   | No   |
| <b>Flow Direction:</b>                    | Northeast to southwest under I-195 (eastbound)  | Northeast to southwest under I-195 (eastbound)   |
| <b>Sedimentation:</b>                     | Unknown   | No   |
| <b>Erosion:</b>                           | No  | No   |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- CB not inspected as part of this review</li> <li>- CB has 6'x6' paved apron within ditch bottom</li> </ul> | <ul style="list-style-type: none"> <li>- Dense vegetation</li> <li>- Outlet marked with a sign</li> <li>- Proposed Trail will cross over near the outlet, recommend culvert extension</li> </ul> |



Catch basin inlet looking southeast



Catch basin inlet looking northwest



Outlet looking northeast



Outlet outfall looking southwest

**Inspector:** Andrew Morrell

**Inspection Date:** 9/28/09

| INSPECTION #4                             | Inlet   | Outlet   |
|---|---|--|
| <b>Approximate Location:</b>              | East side of Trail & I-195 in Segment A west of U.S. Route 1 Interchange  | West side of Trail & I-195 eastbound off ramp to U.S. Route 1 in Segment A west of U.S. Route 1 Interchange – Station 62+05 (Trail stationing) |
| <b>Any nearby existing features:</b>      | I-195/Hannaford Bros. Co.   | I-195/Hannaford Bros. Co.  |
| <b>Size:</b>                              | 36-inch   | 36-inch  |
| <b>Material:</b>                          | RCP Culvert   | RCP Culvert  |
| <b>Condition of Culvert:</b>              | Good  | Good   |
| <b>Does pipe appear to be undersized:</b> | No  | No   |
| <b>Flow Direction:</b>                    | West to east under I-195 EB off-ramp  | West to east under I-195 EB off-ramp   |
| <b>Sedimentation:</b>                     | No  | No   |
| <b>Erosion:</b>                           | No  | No   |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- Low storage area upstream</li> <li>- Dense vegetation</li> <li>- Proposed Trail will cross over the existing inlet, recommend culvert extension</li> </ul> | <ul style="list-style-type: none"> <li>- Dense vegetation</li> <li>- Flows through ditch to pond along U.S. Route 1</li> </ul>                 |



Inlet looking northeast



Inlet ditch looking southeast



Outlet looking southeast



Outlet outfall looking northeast



DeLUCA-HOFFMAN ASSOCIATES, INC.  
CONSULTING ENGINEERS


778 MAIN STREET  
SUITE 8  
SOUTH PORTLAND, MAINE 04106  
TEL. 207 775 1121  
FAX 207 879 0896

**CULVERT INSPECTION REPORT**  
EASTERN TRAIL EXTENSION PROJECT  
From Milliken Mills Road in Old Orchard Beach to  
Thornton Academy in Saco

**Inspector:** Andrew Morrell

**Inspection Date:** 9/28/09

| INSPECTION #5                             | Inlet   | Outlet  |
|---|---|---|
| <b>Approximate Location:</b>              | West side of Trail & U.S. Route 1 in Segment B on western side of I-195 east off ramp to U.S. Route 1 – Station 35+48 (U.S. Route 1 stationing) | West side of Trail & U.S. Route 1 in Segment B on eastern side off I-195 east off-ramp to U.S. Route 1 – Station 67+80 (Trail stationing)   |
| <b>Any nearby existing features:</b>      | I-195 eastbound off ramp  | Detention area  |
| <b>Size:</b>                              | CB with 12-inch   | 12-inch   |
| <b>Material:</b>                          | CMP Culvert   | CMP Culvert   |
| <b>Condition of Culvert:</b>              | Unknown   | OK  |
| <b>Does pipe appear to be undersized:</b> | Unknown   | No  |
| <b>Flow Direction:</b>                    | West to east under off-ramp   | West to east under off-ramp   |
| <b>Sedimentation:</b>                     | Unknown   | No  |
| <b>Erosion:</b>                           | No  | No  |
| <b>General Comments:</b>                  | - CB not inspected as part this review  | - Pipe buried, recommend removal of sediment<br>- Recommend vegetation be trimmed at outlet<br>- This culvert is beneath the EB off-ramp from I-195. No Trail activities are currently contemplated in this culvert |



Inlet catch basin looking north



Outlet looking southwest



Outlet outfall to pond looking northeast

**Inspector:** Andrew Morrell

**Inspection Date:** 9/28/09

| INSPECTION #6                             | Inlet   | Outlet   |
|---|---|--|
| <b>Approximate Location:</b>              | West side of Trail & U.S. Route 1 in Segment B west of I-195 over pass – Station 68+50 (Trail stationing) | East side of Trail & U.S. Route 1 in Segment B west of I-195 overpass – Approx. Station 68+50 (Trail stationing) |
| <b>Any nearby existing features:</b>      | I-195 overpass, off ramp & detention area   | I-195 overpass & off ramp  |
| <b>Size:</b>                              | 48-inch   | 48-inch  |
| <b>Material:</b>                          | RCP Culvert   | RCP culvert  |
| <b>Condition of Culvert:</b>              | Good  | Good   |
| <b>Does pipe appear to be undersized:</b> | No  | No   |
| <b>Flow Direction:</b>                    | North to south under U.S. Route 1   | North to south under U.S. Route 1  |
| <b>Sedimentation:</b>                     | No  | 12-inches (pipe partially buried)  |
| <b>Erosion:</b>                           | No  | No   |
| <b>General Comments:</b>                  | - Dense vegetation<br>- Few small stones  | - Dense vegetation<br>- Culvert partially buried   |



Inlet looking southeast



Inlet pond looking southwest



Outlet looking northwest



Outlet outfall looking southeast



DeLUCA-HOFFMAN ASSOCIATES, INC.  
CONSULTING ENGINEERS

778 MAIN STREET  
SUITE 8  
SOUTH PORTLAND, MAINE 04106  
TEL. 207 775 1121  
FAX 207 879 0896

**CULVERT INSPECTION REPORT**  
EASTERN TRAIL EXTENSION PROJECT  
From Milliken Mills Road in Old Orchard Beach to  
Thornton Academy in Saco

**Inspector:** Andrew Morrell

**Inspection Date:** 9/18/09 Outlet and 9/28/09 Inlet

| INSPECTION #7                             | Inlet  | Outlet   |
|---|--|--|
| <b>Approximate Location:</b>              | South side of I-195 – Station 5041+20<br>(railroad stationing)   | North side of I-195 - Station 5043+92<br>(railroad stationing)   |
| <b>Any nearby existing features:</b>      | I-195  | I-195  |
| <b>Size:</b>                              | 42-inch  | 42-inch  |
| <b>Material:</b>                          | RCP Culvert  | RCP culvert  |
| <b>Condition of Culvert:</b>              | Good   | Good   |
| <b>Does pipe appear to be undersized:</b> | No   | No   |
| <b>Flow Direction:</b>                    | West to east under I-195   | West to east under I-195   |
| <b>Sedimentation:</b>                     | No   | No   |
| <b>Erosion:</b>                           | Minor  | No   |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- Few small stones in stream bed</li> <li>- Dense vegetation</li> <li>- This culvert conveys an unnamed tributary to Goosefare Brook</li> <li>- No Trail activities are contemplated in the area of this culvert</li> </ul> | <ul style="list-style-type: none"> <li>- Dense vegetation at outlet</li> <li>- No trail activities are contemplated in the area of this culvert</li> </ul> |



Inlet looking east



Inlet ditch looking west



Outlet looking west



Outlet outfall looking west



**Inspector:** Andrew Morrell

**Inspection Date:** 9/18/09

| INSPECTION #8                             | Inlet  | Outlet   |
|---|--|--|
| <b>Approximate Location:</b>              | West of Trail in Segment B west of Moody Street - Station 5049+10 (railroad stationing)  | East of Trail in Segment B west of Moody Street - Station 5049+10 (railroad stationing)                      |
| <b>Any nearby existing features:</b>      | Tributary to Goosefare Brook   | Tributary to Goosefare Brook   |
| <b>Size:</b>                              | 6' wide by 1' tall with approx. 2' of cover over top of box  | 6' wide by 1' tall with approx. 2' of cover over top of box  |
| <b>Material:</b>                          | Reinforced concrete box culvert  | Reinforced concrete box culvert  |
| <b>Condition of Culvert:</b>              | Satisfactory   | Satisfactory   |
| <b>Does pipe appear to be undersized:</b> | Unknown – culvert conveys stream flow originating from 42" culvert at I-195, located approx. 515 LF south of this culvert crossing | Unknown  |
| <b>Flow Direction:</b>                    | Northwest to southeast under Trail   | Northwest to southeast under Trail   |
| <b>Sedimentation:</b>                     | Unknown  | Unknown  |
| <b>Erosion:</b>                           | No   | Yes - minor  |
| <b>General Comments:</b>                  | - Dense vegetation to be trimmed   | - Dense vegetation/tree growth to be trimmed<br>- Soil stabilization needed – Recommend riprap be considered |




Inlet looking southeast



Inlet ditch looking west



Outlet looking northwest



Outlet outfall looking southeast


**Inspector:** Andrew Morrell

**Inspection Date:** 9/18/09

| INSPECTION #9                             | Inlet   | Outlet   |
|---|---|--|
| <b>Approximate Location:</b>              | Culvert crosses Moody Street on west side of Trail – Station 5052+85 (railroad stationing)  | Culvert crosses Moody Street on west side of Trail – Station 5053+23 (railroad stationing)   |
| <b>Any nearby existing features:</b>      | Moody Street  | Moody Street   |
| <b>Size:</b>                              | 18-inch   | 18-inch  |
| <b>Material:</b>                          | CMP Culvert   | CMP Culvert  |
| <b>Condition of Culvert:</b>              | Adequate  | Adequate   |
| <b>Does pipe appear to be undersized:</b> | Unknown – no overtopping of Moody Street apparent   | Unknown  |
| <b>Flow Direction:</b>                    | Appears to be west to east under Moody Street (parallel to Trail)   | Appears to be west or east under Moody Street (parallel to Trail)  |
| <b>Sedimentation:</b>                     | 10-inches   | 8-inches   |
| <b>Erosion:</b>                           | No  | Minor  |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- Dense vegetation in ditch</li> <li>- Limited cover over pipe</li> <li>- No flow</li> </ul> | <ul style="list-style-type: none"> <li>- Recommend sediment to be removed from pipe and inlet/outlet areas stabilized with riprap – Pipe to be replaced to allow for ditch modifications.</li> </ul> |



Inlet looking northeast



Inlet ditch looking southwest



Outlet looking southwest



Outlet ditch looking northeast

**Inspector:** Andrew Morrell

**Inspection Date:** 9/18/09

| INSPECTION #10                            | Inlet   | Outlet  |
|---|---|---|
| <b>Approximate Location:</b>              | West of Trail in Segment C west of U.S. Route 1 – Station 5060+50 (railroad stationing)   | East of Trail in Segment C west of U.S. Route 1 - Station 5060+85 (railroad stationing)                           |
| <b>Any nearby existing features:</b>      | Tributary to Goosefare Brook  | Tributary to Goosefare Brook  |
| <b>Size:</b>                              | Unknown   | 3' wide by 3' tall  |
| <b>Material:</b>                          | Unknown   | Granite stone box culvert   |
| <b>Condition of Culvert:</b>              | Unknown   | Adequate  |
| <b>Does pipe appear to be undersized:</b> | Unknown   | No  |
| <b>Flow Direction:</b>                    | West to east under Trail  | West to east under Trail  |
| <b>Sedimentation:</b>                     | Unknown   | 6-inches  |
| <b>Erosion:</b>                           | Major   | Yes   |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- Slope has eroded over inlet</li> <li>- Unable to confirm existing conditions</li> <li>- Recommend inlet repairs and stabilization to improve conditions</li> </ul> | <ul style="list-style-type: none"> <li>- Large stones and debris blocking outflow downstream of outlet</li> </ul> |



Potential inlet looking east



Potential inlet ditch looking northwest



Outlet looking northwest



Outlet outfall looking southeast

Inspector: Andrew Morrell

Inspection Date: 9/18/09

| INSPECTION #11                            | Inlet   | Outlet   |
|---|---|--|
| <b>Approximate Location:</b>              | West of Trail in Segment C west of U.S. Route 1 – Station 5071+00 (railroad stationing)   | East of Trail in Segment C west of U.S. Route 1 - Station 5071+00 (railroad stationing)  |
| <b>Any nearby existing features:</b>      | Goosefare Brook and Innis Brook   | Goosefare Brook and Innis Brook  |
| <b>Size:</b>                              | 7' wide by 4' tall  | 7' wide by 4' tall   |
| <b>Material:</b>                          | Granite stone arch culvert  | Granite stone arch culvert   |
| <b>Condition of Culvert:</b>              | Adequate  | Adequate   |
| <b>Does pipe appear to be undersized:</b> | No  | No   |
| <b>Flow Direction:</b>                    | West to east under Trail  | West to east under Trail   |
| <b>Sedimentation:</b>                     | Minor   | Unknown  |
| <b>Erosion:</b>                           | Minor   | Unknown  |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- Concrete weir broken, needs to be repaired</li> <li>- Significant tree debris has formed dam creating large pond of water upstream of inlet</li> <li>- possible beaver activity</li> </ul> | <ul style="list-style-type: none"> <li>- Water ponded to almost top of structure</li> <li>- Downstream conditions should be inspected</li> </ul> |



Inlet looking east



Inlet upstream ponded area looking north



Outlet looking west



Outlet outfall looking southeast

**Inspector:** Andrew Morrell

**Inspection Date:** 9/18/09

| INSPECTION #12                            | Inlet  | Outlet  |
|---|--|---|
| <b>Approximate Location:</b>              | West of Trail in Segment E east of U. S. Route 1 Station 5079+66 (railroad stationing)                                       | East of Trail in Segment E east of U.S. Route 1 Station 5079+84 (railroad stationing)   |
| <b>Any nearby existing features:</b>      | Seacoast RV site outfall   | Silver Springs Campground   |
| <b>Size:</b>                              | 1.5' wide by 2' tall   | 2' wide by 2' tall  |
| <b>Material:</b>                          | Reinforced concrete box culvert w/headwall   | Granite stone box culvert   |
| <b>Condition of Culvert:</b>              | Good   | Adequate  |
| <b>Does pipe appear to be undersized:</b> | No   | No  |
| <b>Flow Direction:</b>                    | West to east under Trail   | West to east under Trail  |
| <b>Sedimentation:</b>                     | None   | 6-inches  |
| <b>Erosion:</b>                           | None   | Yes   |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- Outfall from Seacoast RV appears to be corroded pipe (rust colored flow)</li> </ul> | <ul style="list-style-type: none"> <li>- Ditch slopes have been stabilized with fabric</li> <li>- Significant erosion has occurred at this location</li> <li>- Recommend additional stabilization of outfall ditch</li> </ul> |



Inlet looking south



Seacoast RV site outfall looking northwest



Outlet looking north



Outlet outfall looking southeast

**Inspector:** Andrew Morrell

**Inspection Date:** 9/18/09

| INSPECTION #13                            | Inlet   | Outlet   |
|---|---|--|
| <b>Approximate Location:</b>              | West of Trail in Segment E east of U. S. Route 1 – located within a natural ravine<br>Station 5085+80 (railroad stationing) | East of Trail in Segment E east of U.S. Route 1 – located within a natural ravine<br>Station 5085+80 (railroad stationing)   |
| <b>Any nearby existing features:</b>      | Tributary to Goosefare Brook  | Tributary to Goosefare Brook   |
| <b>Size:</b>                              | 3' wide by 3' tall  | May be 3' x 3'   |
| <b>Material:</b>                          | Granite stone box culvert   | Granite stone box culvert  |
| <b>Condition of Culvert:</b>              | Adequate  | Poor due to erosion  |
| <b>Does pipe appear to be undersized:</b> | No  | Unknown  |
| <b>Flow Direction:</b>                    | West to east under Trail  | Appears to be west to east under Trail   |
| <b>Sedimentation:</b>                     | 6-inches  | Unknown  |
| <b>Erosion:</b>                           | Yes   | Yes  |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- Some stones have fallen off the box culvert and are blocking inlet</li> </ul>      | <ul style="list-style-type: none"> <li>- Significant erosion found</li> <li>- Tree debris blocking access to outlet</li> <li>- Unable to confirm culvert location or size</li> <li>- Slope has partially eroded over outlet</li> <li>- Recommend stabilization of outfall</li> </ul> |



Inlet looking southeast



Upstream inlet ditch looking northwest



Outlet looking northwest



Outlet outfall looking northeast

**Inspector:** Andrew Morrell

**Inspection Date:** 9/18/09

| INSPECTION #14                            | Inlet  | Outlet  |
|---|--|---|
| <b>Approximate Location:</b>              | West of Trail in Segment E east of U. S. Route 1 – located within a natural ravine Station 5088+11 (railroad stationing) | East of Trail in Segment E east of U.S. Route 1 – located within a natural ravine Station 5088+11 (railroad stationing) |
| <b>Any nearby existing features:</b>      | Tributary to Goosefare Brook   | Tributary to Goosefare Brook  |
| <b>Size:</b>                              | 3' wide by 3' tall   | 3' wide by 3' tall  |
| <b>Material:</b>                          | Granite stone box culvert  | Granite stone box culvert   |
| <b>Condition of Culvert:</b>              | Adequate   | Adequate  |
| <b>Does pipe appear to be undersized:</b> | No   | No  |
| <b>Flow Direction:</b>                    | West to east under Trail   | West to east under Trail  |
| <b>Sedimentation:</b>                     | 6-inches   | 18-inches   |
| <b>Erosion:</b>                           | Yes  | Yes   |
| <b>General Comments:</b>                  | - Tree debris/trash at inlet should be removed   | - Erosion could be remedied with some stabilization such as riprap  |



Inlet looking southeast



Inlet ditch looking northwest



Outlet looking northwest



Outlet outfall looking southeast

Inspector: Andrew Morrell

Inspection Date: 9/18/09

| INSPECTION #15                            | Inlet  | Outlet   |
|---|--|--|
| <b>Approximate Location:</b>              | West of Trail in Segment E east of U. S. Route 1 – located within natural ravine<br>Station 5091+01 (railroad stationing)  | East of Trail in Segment E east of U.S. Route 1 – located within a natural ravine<br>Station 5090+80 (railroad stationing) |
| <b>Any nearby existing features:</b>      | Tributary to Goosefare Brook   | Tributary to Goosefare Brook   |
| <b>Size:</b>                              | Possibly 2' x 2'   | 2' wide by 2' tall   |
| <b>Material:</b>                          | Probable granite box   | Granite stone box culvert  |
| <b>Condition of Culvert:</b>              | Poor – eroded inlet banks  | Adequate   |
| <b>Does pipe appear to be undersized:</b> | Unknown  | No   |
| <b>Flow Direction:</b>                    | Appears to be west to east under Trail   | West to east under Trail   |
| <b>Sedimentation:</b>                     | Unknown  | 6-inches   |
| <b>Erosion:</b>                           | Yes  | Yes  |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- Slope has eroded onto inlet and covered what looks like an existing granite box culvert</li> <li>- Unable to confirm existing culvert conditions</li> </ul> | <ul style="list-style-type: none"> <li>- Downstream tree debris in channel below outlet is blocking outflow</li> </ul>     |



Potential inlet looking southeast



Potential inlet ditch looking north



Outlet looking northwest



Outlet outfall looking southeast



## CULVERT INSPECTION REPORT

### EASTERN TRAIL EXTENSION PROJECT

From Milliken Mills Road in Old Orchard Beach to  
Thornton Academy in Saco

Inspector: Andrew Morrell

Inspection Date: 9/18/09

| INSPECTION #16                            | Inlet  | Outlet   |
|---|--|--|
| <b>Approximate Location:</b>              | West of Trail in Segment E east of U. S. Route 1 – located within a natural ravine Station 5093+46 (railroad stationing)   | East of Trail in Segment E east of U.S. Route 1 – located within a natural ravine Station 5092+96 (railroad stationing)  |
| <b>Any nearby existing features:</b>      | Tributary to Goosefare Brook   | Tributary to Goosefare Brook   |
| <b>Size:</b>                              | Possibly 2' x 2'   | 2' x 2'  |
| <b>Material:</b>                          | Granite box  | Granite box  |
| <b>Condition of Culvert:</b>              | Poor due to blocked inlet  | Poor due to eroded slopes and debris   |
| <b>Does pipe appear to be undersized:</b> | Unknown  | Unknown  |
| <b>Flow Direction:</b>                    | Appears to be west to east under Trail   | Appears to be west to east under Trail   |
| <b>Sedimentation:</b>                     | Unknown  | Unknown  |
| <b>Erosion:</b>                           | Minor  | Yes  |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- Inlet plugged with eroded soils, roots &amp; tree debris</li> <li>- Unable to locate pipe culvert</li> <li>- Appears to be remnants of 2' x 2' granite stone box culvert</li> </ul> | <ul style="list-style-type: none"> <li>- Outlet covered by large tree and root system</li> <li>- Unable to locate pipe/culvert</li> <li>- Erosion could be remedied with stabilization</li> <li>- Appears to be remnants of 2' x 2' granite stone box culvert</li> </ul> |



Potential inlet looking east



Potential inlet ditch looking north



Potential outlet looking northwest



Potential outlet outfall looking southeast



DeLUCA-HOFFMAN ASSOCIATES, INC.  
CONSULTING ENGINEERS

778 MAIN STREET  
SUITE 8  
SOUTH PORTLAND, MAINE 04106  
TEL. 207 775 1121  
FAX 207 879 0896

**CULVERT INSPECTION REPORT**  
EASTERN TRAIL EXTENSION PROJECT  
From Milliken Mills Road in Old Orchard Beach to  
Thornton Academy in Saco

**Inspector:** Andrew Morrell

**Inspection Date:** 9/18/09

| INSPECTION #17                            | Inlet  | Outlet  |
|---|--|---|
| <b>Approximate Location:</b>              | West of Trail in Segment E east of U. S. Route 1 – located within a natural ravine Station 5099+29 (railroad stationing)   | East of Trail in Segment E east of U.S. Route 1 – located within a natural ravine Station 5099+18 (railroad stationing) |
| <b>Any nearby existing features:</b>      | Tributary to Goosefare Brook   | Tributary to Goosefare Brook  |
| <b>Size:</b>                              | RR records show 2.5' x 2'  | Unknown – RR records show 2.5' x 2'   |
| <b>Material:</b>                          | Granite box  | Granite box   |
| <b>Condition of Culvert:</b>              | Unknown – obscured by eroded slopes  | Obscured by eroded slopes   |
| <b>Does pipe appear to be undersized:</b> | Unknown  | Unknown   |
| <b>Flow Direction:</b>                    | Appears to be west to east under Trail   | Appears to be west to east under Trail  |
| <b>Sedimentation:</b>                     | Unknown  | Unknown   |
| <b>Erosion:</b>                           | Unknown  | Unknown   |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- Pipe/culvert not found</li> <li>- Could be submerged in water</li> <li>- Tree debris exists as well</li> <li>- Remnants of granite stone present</li> </ul> | <ul style="list-style-type: none"> <li>- Pipe/culvert not found</li> <li>- Could be submerged in water</li> </ul>       |



Potential inlet looking east



Potential inlet collection area looking northwest



Potential outlet looking northwest



Potential outlet outfall looking southeast



DeLUCA-HOFFMAN ASSOCIATES, INC.  
CONSULTING ENGINEERS

778 MAIN STREET  
SUITE 8  
SOUTH PORTLAND, MAINE 04106  
TEL. 207 775 1121  
FAX 207 879 0896

**CULVERT INSPECTION REPORT**  
EASTERN TRAIL EXTENSION PROJECT  
From Milliken Mills Road in Old Orchard Beach to  
Thornton Academy in Saco

**Inspector:** Andrew Morrell

**Inspection Date:** 9/18/09

| INSPECTION #18                            | Inlet   | Outlet  |
|---|---|---|
| <b>Approximate Location:</b>              | West of Trail in Segment E southwest of Cascade Road (Route 98)   | West of Trail in Segment E southwest of Cascade Road (Route 98)   |
| <b>Any nearby existing features:</b>      | Abutting residence to northwest   | Abutting residence to northwest   |
| <b>Size:</b>                              | 12-inch   | 12-inch   |
| <b>Material:</b>                          | CMP culvert   | CMP culvert   |
| <b>Condition of Culvert:</b>              | Eroded at bottom  | Eroded at bottom  |
| <b>Does pipe appear to be undersized:</b> | No  | No  |
| <b>Flow Direction:</b>                    | Southwest to northeast along Trail (west side)  | Southwest to northeast along Trail (west side)  |
| <b>Sedimentation:</b>                     | 6-inch  | None  |
| <b>Erosion:</b>                           | Minor   | None  |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- Culvert provides access for abutting residence to existing trail. This culvert does not pass beneath trail.</li> <li>- Minor flow</li> <li>- Tree debris blocking inlet</li> </ul> | <ul style="list-style-type: none"> <li>- Small flow (less than 1-inch)</li> <li>- Outlet 6-inches above ground</li> </ul> |



Access to abutting residence over culvert looking northwest from existing trail



Inlet looking northeast



Outlet looking south

Inspector: Andrew Morrell

Inspection Date: 9/18/09

| INSPECTION #19                            | Inlet  | Outlet  |
|---|--|---|
| <b>Approximate Location:</b>              | East of Trail in Segment E southwest of Cascade Road (Route 98)  | West of Trail in Segment E northeast of Cascade Road (Route 98)   |
| <b>Any nearby existing features:</b>      | Tributary to Mill Brook  | Tributary to Mill Brook – passes under Cascade Road   |
| <b>Size:</b>                              | Unknown (unable to measure) – RR records show 4' x 4'  | 60-inch   |
| <b>Material:</b>                          | Granite stone box culvert  | CMP culvert   |
| <b>Condition of Culvert:</b>              | Poor   | Good  |
| <b>Does pipe appear to be undersized:</b> | Unknown  | No  |
| <b>Flow Direction:</b>                    | Southwest to northwest (under Trail and Cascade Road)  | Southwest to northwest (under Trail and Cascade Road)   |
| <b>Sedimentation:</b>                     | Unknown  | 18-inches   |
| <b>Erosion:</b>                           | Unknown  | None  |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- Inlet has ponded water 4'-6' deep at granite box</li> <li>- Unknown structure size (approx. 6' wide x 4'-6' deep)</li> <li>- No signs of 60" CMP</li> <li>- Length to outlet is approximately 150 feet</li> </ul> | <ul style="list-style-type: none"> <li>- Culvert embedded into ground, thus flow potential has been reduced</li> <li>- Flowing with 14" water at time of visit</li> </ul> |



Inlet looking north



Inlet looking south



Outlet outfall looking north



Outlet looking south



DeLUCA-HOFFMAN ASSOCIATES, INC.  
CONSULTING ENGINEERS


778 MAIN STREET  
SUITE 8  
SOUTH PORTLAND, MAINE 04106  
TEL. 207 775 1121  
FAX 207 879 0896

**CULVERT INSPECTION REPORT**  
EASTERN TRAIL EXTENSION PROJECT  
From Milliken Mills Road in Old Orchard Beach to  
Thornton Academy in Saco

**Inspector:** Andrew Morrell

**Inspection Date:** 9/18/09

| INSPECTION #20                            | Inlet   | Outlet   |
|---|---|--|
| <b>Approximate Location:</b>              | West of Trail in Segment F northeast of Old Cascade Road  | East of Trail in Segment F northeast of Old Cascade Road   |
| <b>Any nearby existing features:</b>      | Abutting residences and pole line to west   | Milliken Mills Pond downstream (east)  |
| <b>Size:</b>                              | Unknown   | Unknown  |
| <b>Material:</b>                          | Unknown   | Unknown  |
| <b>Condition of Culvert:</b>              | Unknown   | Unknown  |
| <b>Does pipe appear to be undersized:</b> | Unable to determine   | Unable to determine  |
| <b>Flow Direction:</b>                    | Appears to be west to east (under Trail)  | Appears to be west to east (under Trail)   |
| <b>Sedimentation:</b>                     | Unknown   | Unknown  |
| <b>Erosion:</b>                           | None  | Minor  |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- No culvert found however based on downstream conditions it appears one exists here, may be plugged/buried</li> <li>- No flowing water found</li> <li>- Vegetated ditch filled with brush/grass debris</li> </ul> | <ul style="list-style-type: none"> <li>- No culvert found, may be plugged/buried</li> <li>- Water seeps out of ground (less than 2" deep)</li> <li>- Water flows through ditch to Milliken Mills Pond</li> </ul> |



Potential inlet looking northeast



Potential outlet outfall looking west



DeLUCA-HOFFMAN ASSOCIATES, INC.  
CONSULTING ENGINEERS

778 MAIN STREET  
SUITE 8  
SOUTH PORTLAND, MAINE 04106  
TEL. 207 775 1121  
FAX 207 879 0896

# CULVERT INSPECTION REPORT

## EASTERN TRAIL EXTENSION PROJECT

From Milliken Mills Road in Old Orchard Beach to  
Thornton Academy in Saco

**Inspector:** Andrew Morrell

**Inspection Date:** 9/18/09

| INSPECTION #21                            | Inlet  | Outlet   |
|---|--|--|
| <b>Approximate Location:</b>              | West of Trail in Segment F northeast of Old Cascade Road   | East of Trail in Segment F northeast of Old Cascade Road   |
| <b>Any nearby existing features:</b>      | Abutting residences and pole line to west  | Milliken Mills Pond downstream (east)  |
| <b>Size:</b>                              | 30-inch  | 40" wide by 18" tall   |
| <b>Material:</b>                          | Steel culvert with granite stone headwall  | Granite stone box culvert  |
| <b>Condition of Culvert:</b>              | Signs of some corrosion  | Adequate   |
| <b>Does pipe appear to be undersized:</b> | No   | No   |
| <b>Flow Direction:</b>                    | West to East (under Trail)   | West to East (under Trail)   |
| <b>Sedimentation:</b>                     | 3-inches   | 6 to 12-inches (varies across outlets)   |
| <b>Erosion:</b>                           | Minor  | None   |
| <b>General Comments:</b>                  | <ul style="list-style-type: none"> <li>- Slight flow of water (less than 1")</li> <li>- Ditch has dense vegetation and tree debris that should be removed</li> </ul> | <ul style="list-style-type: none"> <li>- No flow exiting outlet</li> <li>- Build-up sediment restricting flow</li> <li>- No signs of steel pipe</li> </ul> |



Inlet looking east



Inlet ditch looking west from proposed Trail



Outlet looking west



Outlet outfall looking east to Milliken Mills Pond

**Eastern Trail –Thornton Academy in Saco, Maine to Milliken Mills Road in OOB,  
Maine PIN # 13340.00**

**Summary of Existing Granite Box Culverts at 6 locations**

| <b>Railroad Stationing Location</b> | <b>Drainage Area (ac)</b> | <b>Existing Size</b>  | <b>Flow –Q50 (cfs)</b> | <b>Flowing Full Capacity (cfs)</b> |
|-------------------------------------|---------------------------|-----------------------|------------------------|------------------------------------|
| 5079+66                             | 6.76                      | 2' x 2' Granite Box   | 31.48                  | 23.04                              |
| 5085+80                             | 27.92                     | 3' x 3' granite box   | 58.87                  | 26.85                              |
| 5088+11                             | 10.91                     | 3' x 3' granite box   | 30.91                  | 26.85                              |
| 5091+01                             | 43.12                     | 2' x 2' Granite Box   | 83.80                  | 24.09                              |
| 5093+46                             | 6.54                      | 2' x 2' Granite Box   | 15.96                  | 20.96                              |
| 5099+29                             | 74.75                     | 2.5' x 2' Granite Box | 93.18                  | 12.21                              |

Notes:

1. The drainage areas are based on watershed limits extrapolated from the City of Saco Aerial Mapping with 2' contour intervals.
2. All culvert sizes are based on measurements provided by Dow and Coulombe Inc.
3. The 50 year storm event flow values are based on the following methods as outlined in the Maine DOT Highway Design Guide: Potters Method, Benson Method, BPR1021 Method, Rational Method and USGS methods. Flow values for the applicable methods were calculated and an average flow rate determined.
4. Flowing full culvert capacity is based on the manning's formula where n=0.013. Slope values are based on invert information provided by Dow and Coulombe Inc.