

APPENDIX C

Culvert Inspection Reports



DeLUCA-HOFFMAN ASSOCIATES, INC.
CONSULTING ENGINEERS

778 MAIN STREET
SUITE 8
SOUTH PORTLAND, MAINE 04106
TEL. 207 775 1121
FAX 207 879 0896

CULVERT INSPECTION REPORT
EASTERN TRAIL EXTENSION PROJECT
From Milliken Mills Road in Old Orchard Beach to
Thornton Academy in Saco

Inspector: Andrew Morrell

Inspection Date: 9/28/09

INSPECTION #1	Inlet	Outlet
Approximate Location:	Thornton Academy Campus parking area for middle school southeast of baseball field	Thornton Academy Campus parking area for middle school southeast of baseball field
Any nearby existing features:	Thornton Academy	Thornton Academy
Size:	CB with 8-inch outlet	8" PVC
Material:	PVC Culvert	PVC Culvert
Condition of Culvert:	Good	Good
Does pipe appear to be undersized:	No	No
Flow Direction:	North to south under parking area	North to south under parking area
Sedimentation:	No	Unknown
Erosion:	Yes	Unknown
General Comments:	- CB not inspected as part of this review - Minor erosion along EOP to be repaired	- Outlet cannot be found - May be buried by piled debris



Catch basin inlet looking southeast



Catch basin inlet looking northwest



Potential outlet ditch looking southeast